



Dashboard Home Search

School Name & Location



SAU Name RSU 63/MSAD 63
School Name Holden School
School Address 590 Main Road
Holden
ME
04429

School CountyPenobscotSchool Phone Number207-843-7828Grades02-04School TypePublic

Notes/Comments:

Site & Infrastructure

of Acres 8
Water System Well(s)
Sewage Waste Disposal System On Site Septic
Site Connected to Public Sidewalks No
Separate Bus/Car Traffic loops No
In the 100 Year Floodplain No
Recreational field / area funded through the federal LWCF program No
Notes/Comments:

School Building Features

Building StatusOpenShared BuildingSingle SchoolYear of Original Construction1954Historical StatusNo

Year Addition Constructed	1974,1989
Year of Substantial Renovations (>50%)	2021
# of Stories	1
# of Students	126
Square Footage Per Student	200
Square Footage of Building	25300
# of Additional Spaces	0
Total Square Footage of Additional Spaces	0
Notes/Comments:	

HVAC System & Air Quality

Mechanical Ventilation Building Coverage 34% to 66%

Type of Mechanical Ventilation Energy Recovery Ventilation (ERV)

>13 MERV (Min Efficiency Reporting Values)

Air Conditioning Building Coverage 1% to 33%

Type of Air Conditioning
Window Unit

Heating System Steam/Hot Water Heating System

Heating Energy Source Propane

Age of Heating System Over 20 Years

Control System Building Management System/Building Automated System (BAS)

On-Site Power Generation Source

Electrical Power System

Three Phase

Yes

% of Building w/ LED Lighting

1% to 33%

% of Building w/ Lighting Controls 1% to 33%

Notes/Comments:

Back-Up Generator

Building Type

Roof Structure Wood

Roof Pitch Pitched

Building Exterior Siding

Masonry, Vinyl

Exterior Wall Structure

Masonry Block/Brick, Wood Frame

Interior Wall Structure Wood Stud, Masonry Block/Brick

Documented Structural Deficiencies

Unknown

Notes/Comments:

Site & Building Accessibility

ADA Accessible Site

Parking and Passenger Loading Zones

Building Approach/Ramps

No

Building Entrance

No

Playgrounds No

Ballfield(s) Yes

ADA Building Accessibility

Alternative Accessible Entrance

Emergency Exits

Door Clearance

N/A

Yes

Room and Exit Signs
Interior Signs
No
Restrooms
Yes
Drinking Fountains
No

Water Bottle Filling Station

Notes/Comments:

Hazardous Materials & Environmental Conditions

Hazardous Material/Condition	Identified in Survey and Remediated	Identified in Survey and Not Remediated	Not Identified in Survey	Not Surveyed	Unknown
Radon					✓
Mold				√	
Air Quality				√	
Lead					√
Asbestos	√				
PCBS				√	
PFAS				√	

Recurring Flooding

Yes

Notes/Comments:

Educational Program & Planning

SAU Reported Sufficient Space	
PreK/Early Childhood	N/A
General Classrooms	Yes
Science Classrooms	N/A
Special Ed	Yes
Health Clinic	Yes
Kitchen/Cafeteria	Yes
Physical Education	Yes
Library	Yes
Music	Yes

Gender Neutral Facilities

Guidance/Career Prep

Bathrooms Yes
Locker/Changing Rooms N/A
Showers N/A

Yes

N/A

Yes

SAU Long-Term Plan (10 Years)

Consolidation

Notes/Comments:

Art

STEM/STEAM

Fire Protection System

% of Fire Alarm Coverage 67% to 100% % of Sprinkler System Coverage 67% to 100% % of Smoke Alarm Coverage 67% to 100% Water Source Used for Fire Protection Private

Notes/Comments:

Security/Safety

Single Point of Entry No

Location of Office at Main Entrance

Security Features of Main Entrance Camera/Video Surveillance System, Intercom Communications System, Secure Entrance Vestibule

Security Features of Building Classroom Doors with Lockable Hardware,Exterior Speaker System,Exterior Door Numbering Clearly Visible from Inside & Outside of Door

Notes/Comments:

Back to Search